Radio Holland USA
8043 Gulf Freeway
Houston, TX 77017
Phone: 713-941-2290 Fax: 713-378-2194
E-Mail: houston@serviceradiohollandusa.com

Radio Holland Group
Global Service House

SERVICE REPORT

TASK ID: 199366

Office	HOUSTOM	Vessel	TI BROOKS
Owners		IMO No.	MMSI
Agents		Call Sign	Flag ' USA
Port and Berth		Inmarsat C No.	
Invoice to	984110	ETA	ETD
Orderno			
Date of Request			

SVC type: ☒ Request ☐ Warranty ☐ Contract
Charge to: ☐ Owner ☐ Agent ☐ Others

Equipment	Serial number
3 EPIRBS TESTING	
Software version if applicable	

a) Fault reported b) Action taken c) Final Check

A) TESTING OF 3 EPIRBS IN SHOP.

1) RV GYRE,
ACR-RLB-35 CAT-1 S.NO 4105
Battery expiry, 03-2013/ OK Hydro static release expiry, 07-2014/ OK, NOAA sticker Expiry 11-22-2012/ OK
Code: 2DCC56A012FFBFF/ OK, serial code 3664105/ok EPIRB Frequency, 406.0258 Mhz/ OK , Homing: 121.5 /ok
EPIRB TESTED IN SHOP ITS WORKING NORMAL..

2) R/V GEO EXPLORER,
ACR-RLB-38, S.NO 10966.
Battery expiry, 08-2016/ OK Hydro static release expiry, 10-2012. NOAA sticker Expiry 10-07-2012.
Code: 2DCC5ED5ACFFBFF/ OK, Serial Code; 36610966/ OK EPIRB Frequency, 406.0369Mhz/ OK
EPIRB TESTED IN SHOP ITS WORKING NORAMAL.

3) R/V BROOKS MCCALL,
MCMURDO E5 SMARTFIND, S.NO 100-15096.
Battery expiry: 06/2014/ OK, Hydrostatic release expiry:01-2013/ OK, NOAA sticker expiry: 04-07-2013
Code: ADCD40EBE00028D/ OK, Serial Code: 366-2808/ OK, EPIRB Frequency: 406.0280.
EPIRB TESTED IN SHOP ITS WORKING NORMAL.

Note: epirb no 3,s mounting bracket is cracked and need to be replaced with New one.

Cause code: INSPECTION Solution code: CERTIFIED Outcome category: FTR

Material (S)upplied/(R)emoved

Qty.	Part no.	Description	Serial No.	Price	S	R

Labour		---------- Time-----		------Hours---------				Office Use Only			
Date	Service Tech.	From	To	Onboard	Shop/Wait	Travel	Zone/Miles	IND	CODE	TOTAL	OTB
10-03	ALFRED SAMUEL	0900	1130		2.5						

Service Engineer (Name/Signature)
ALFRED SAMUEL
FCC LIC# DM-GB-009173

Date: 10-03-2011

Master/Authorized Representative signature. & Ship stamp

Customer Satisfaction
☺ ☒
☹ ☐
☹ ☐

Work completed: YES ☒ NO ☐ Customer comments: YES ☐ NO ☒

Number of sheets 1 of 1

Service rendered is subject to general (service) conditions of Radio Holland, please contact your representative for a copy of these general (service) conditions
* Return travel may be omitted due to variations out of our control such as transportation delays etc.