

THE INTEROCEAN MARITIME ENTERPRISES (PVT) LTD.,

UNIT F-32, 1st FLOOR, 'LUCKY PLAZA', ST. ANTHONY'S MAWATHA, COLOMBO - 03

COMPASS DEVIATION CERTIFICATE

NAME OF VESSEL : *GEO EXPLORER*
 POSITION : *COLOMBO HARBOUR Limit*
 MAGNETIC COMPASS : *SPERRY*
 VARIATION : *3°W*



Ship's Head by Standard Compass		Deviations	Ship's Head by Standard Compass		Deviations
000°	North	<i>5°E</i>	180°	South	<i>2°W</i>
022°	N.N.E	<i>6½°E</i>	202°	S.S.W	<i>3°W</i>
045°	North East	<i>8°E</i>	225°	South West	<i>4°W</i>
067°	E.N.E	<i>7°E</i>	247°	W.S.W	<i>4½°W</i>
090°	East	<i>6°E</i>	270°	West	<i>5°W</i>
112°	E.S.E	<i>4°E</i>	292°	W.N.W	<i>2½°W</i>
135°	South East	<i>2°E</i>	315°	North West	<i>NIL</i>
157°	S.S.E	<i>½°E</i>	337°	N.N.W	<i>2°E</i>

Plan	Description of Correctors	N° and Size of Correctors	Distance from Ends of Magnets to Centre of Compass Needles
	Port pieces	BLUE End	
	Fore and Aft Magnets	Length cm Dia. cm	
	Starboard pieces	BLUE End	
	Athwartship Magnets pieces	RED End	
	Flinders Bar pieces	Length Dia.	
	Quadrantal Correctors <i>2</i> pieces	Length Dia.	
	Vertical Magnets Heeling err pieces		

The deviations were obtained by means of Gyro Compass and known distant bearings. I hereby declare that the compass of the above named vessel this day have been examined and where necessary, adjusted by me.

Issued on this *28th* DAY OF *January* 2007 at *Colombo*.

Capt. Tilak Wickramasinghe
 Compass Adjuster



MARINE CONSULTANTS, AGENTS, SURVEYORS & SHIP REPAIRERS

PHONE : 2577566, 2577567 MOBILE : 0712 723227, 0712 737380, 0712 772175

FAX : 2577567 E-Mail : interocean@sl.lanka.net